Attachment 5
General Minerals Analysis

	Method Number
Boron	SW 6010
Conductivity	EPA 120.1
Chloride	EPA 325.2
pH	EPA 150-1
Sodium	AA method 7770
Sulfate	EPA 375.2